IHLEFABRICATIONSLLC[®] INSTALLATION INSTRUCTIONS

CLEAN GRAIN BOOT LINER KIT

CASE IH[®] FLAGSHIP SERIES

P/N: IF110417BK (73399500R)

All **Ihle Fabrications** products are made in the USA using the best materials to provide quality auger liner replacement parts. **Ihle Fabrications** a familyowned agriculture and fabrication business and stands behind our craftsmanship.











HARDOX[®] WEAR PLATE

Hardox[®] Wear Plate is the world's leading abrasion-resistant (AR) steel. Enjoy the benefits of guaranteed toughness in our products made with Hardox[®] Wear Plate.



TOOLS NEEDED

Welder Locking C-Clamps Grinder Silicone/Sealer **ITEMS INCLUDED**

Liner Pieces (8)

PH: 515-329-8050

4780 NW 158TH AVE. POLK CITY, IA 50226

THANK YOU FOR YOUR BUSINESS

INSTALLATION INSTRUCTIONS

CLEAN GRAIN BOOT LINER KIT

Carefully follow instructions, match all pieces from the kit with the reference numbers on the following pages. *Hash marks etched into the pieces will line up if they are in the correct order.*


Step 1: Before welding, ensure each piece is clamped as tight as possible.

Step 2: Tack weld each piece, in numbered order.

Step 3: When all pieces have been tack welded in place, then fully weld each piece, using high heat.

Step 4: Grind all welds smooth to ensure clearance.


Step 5: When reinstalling, the foam seal will have to be discarded. Reseal any remaining gap using a CNH (or other preferred) silicone.



REACH OUT TO OUR TEAM

P: 515-329-8050 E: INFO@IHLEFABRICATIONS.COM

QUESTIONS?



REACH OUT TO OUR TEAM

P: 515-329-8050 E: INFO@IHLEFABRICATIONS.COM

WWW.IHLEFABRICATIONS.COM




REACH OUT TO OUR TEAM

P: 515-329-8050 E: INFO@IHLEFABRICATIONS.COM

WWW.IHLEFABRICATIONS.COM

IHLEFABRICATIONSLLC[®]



Refer to numbered pieces during install as needed.



REACH OUT TO OUR TEAM

P: 515-329-8050 E: INFO@IHLEFABRICATIONS.COM

QUESTIONS?



Install the top ring flush to the outside

REACH OUT TO OUR TEAM

P: 515-329-8050 E: INFO@IHLEFABRICATIONS.COM

QUESTIONS?

Tack weld top ring on outside only, as shown below.



REACH OUT TO OUR TEAM

P: 515-329-8050 E: INFO@IHLEFABRICATIONS.COM

QUESTIONS?

IHLEFABRICATIONSLLC[®]



REACH OUT TO OUR TEAM

P: 515-329-8050 E: INFO@IHLEFABRICATIONS.COM


QUESTIONS?

After installing top & bottom rings (#1 & #2) Install #3. Clamp in place, then tack weld to #1. (**DO NOT** tack weld to the housing.)

QUESTIONS?

REACH OUT TO OUR TEAM


P: 515-329-8050 E: INFO@IHLEFABRICATIONS.COM



REACH OUT TO OUR TEAM

P: 515-329-8050 E: INFO@IHLEFABRICATIONS.COM


QUESTIONS?



REACH OUT TO OUR TEAM

P: 515-329-8050 E: INFO@IHLEFABRICATIONS.COM


QUESTIONS?



REACH OUT TO OUR TEAM

P: 515-329-8050 E: INFO@IHLEFABRICATIONS.COM

WWW.IHLEFABRICATIONS.COM



REACH OUT TO OUR TEAM

P: 515-329-8050 E: INFO@IHLEFABRICATIONS.COM

WWW.IHLEFABRICATIONS.COM

Clamp #8 on hinge side of the boot. Plug weld all holes.



REACH OUT TO OUR TEAM

P: 515-329-8050 E: INFO@IHLEFABRICATIONS.COM

QUESTIONS?